



BLOCKS MARKED FOR REMOVAL

RESTORATION IS INCIDENTAL TO CONTRACTOR'S COST AND DISTURBED AREAS SHOULD BE LIMITED TO AN 18" WIDE STRIP




DRIVEWAY BLOCKS




CONTRACTOR DAMAGED ADJ. BLOCK

REPLACE ADJACENT BLOCK WHEN OVER A HALF OF A FOOT LARGER AT CONTRACTOR'S COST




ADJ. BLOCK ALREADY DAMAGED




SAFETY

ALL BARRICADES MUST BE CLEAN, IN GOOD CONDITION AND LIGHTS MUST BE OPERABLE.




ROOTS & FEATURES



SITE PREP.

BACKFILL AND RESTORATION SHOULD BE DONE WITHIN 24 HOURS OF POURING CONCRETE. ALL RESTORED AREAS MUST HAVE MOVABLE SLOPES



UTILITIES

DIGGERS HOTLINE
 (800) 242-8511 (414) 259-1181
 www.digger hotline.com

THESE DETAILS ARE INTENDED TO SERVE AS A GUIDE FOR MOST COMMON SITUATIONS, IN ALL CASES SIDEWALK SHALL BE INSTALLED PER CONTRACT SPECIFICATIONS. ALL QUESTIONS OR DISCREPANCIES SHOULD BE ADDRESSED TO THE VILLAGE ENGINEER OR THE VILLAGE ENGINEER'S DESIGNATED REPRESENTATIVE.



Village of Whitefish Bay	
Standard Detail	
SIDEWALK BLOCK NOTES	
Scale = None	REV-JUN06
Sheet 1 of 1	DETAIL 3